

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



2009-07-25 Concrete for pool E6



Balcony walls is getting installed at the rowhouse



Planting bushes at phase.
Soi between C1 and C8



Restaurant building from the back
Most 6 pipings are installed



The restaurant has more walls bricked



Rowhouse H105 painting work

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Doors and windows are installed in rowhouse H105



Painting work att F4 small villa



Bathroom work in F4 small villa



Ceiling work at F4 small villa



Pool E6



Sala work at villa E5

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Tiling work almost finished at pool E5



Tiling work at villa E5 about to continue



Planting of flowers and bushes have begun at villa E1-E4



Plants at E2-E3



Plants at E1-E2



Sala work at villa E1 in progress

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Bathroom at villa E1



Some plants behind villa E1



Sala work at villa F1



Tiling of pool F1 continues



Sala work at villa F2 continues



Poolarea at villa F2 in progress

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Pool E8 lined up and ready to start



Pool E9 soon ready to start



Fixing work at villa A9



Fixing work at villa A9



Wall work at villa A10



Wall at villa C12-C14 almost finished

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Plantation is coming up nicely at phase 1



Plants arrived to Villa A3



Sliding doors installation in rowhouse H105



Fence ready to be painted in rowhouse H105



Wall work at balcony H105



More walls are coming up at the Apartment building

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



More plastering in progress inside the apartments



Villa C9 bambuwall



Villa C9 bambuwall. Picture taken from parking area



More plastering in the apartments
This is G102 that is finished



Painting work can soon be started in G102-G104



Picture from G103

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



Door columns are beeing made



Apartment G305




View from G302



More balcony walls are coming up, now at H103



G302 has most of the pipings installed



Units at 3rd floor has an open space up to the ceiling foolowing the roof structure

**Progress Report
Malee Seaview and Sai Naam Area
2009-07-30**



View up to the loft in G302



Bedroom G302



View from bedroom G302



View from balcony G302



Rowhouse H105



Rowhouse H104

Progress Report Malee Seaview and Sai Naam Area 2009-07-30



G302



Restaurant building floor 2



Restaurant building



Sala work at E5



Sala work at F1



Painting work at the rowhouse