

# Progress Report Malee Seaview and Sai Naam Area 2010-08-24



Wallwork at A7



Wallwork at A7



Wallwork at A7



Wallwork at A7



Wallwork at A7



Toilet & Showerbuilding

**Progress Report  
Malee Seaview and Sai Naam Area  
2010-08-24**



**G101 before furniture**



**G101 before furniture**



**G101 before furniture**



**Kitchen installed**



**G205**




**G204**

# Progress Report Malee Seaview and Sai Naam Area 2010-08-24



G203



G203 a few days later



G203



G205



Index Furniture delivery



Index Furniture delivery

**Progress Report  
Malee Seaview and Sai Naam Area  
2010-08-24**



**Index Furniture delivery**



**Installation of furniture in  
G101, G106, G201, G207**



**Installation of furniture in  
G101, G106, G201, G207**



**Installation of furniture in  
G101, G106, G201, G207**



**Installation of furniture in  
G101, G106, G201, G207**



**Installation of furniture in  
G101, G106, G201, G207**

**Progress Report  
Malee Seaview and Sai Naam Area  
2010-08-24**



**Installation of furniture in  
G101, G106, G201, G207**



**After installation  
G101**



**After installation  
G101**



**After installation  
G101**



**After installation  
G101**



**After installation  
G101**

**Progress Report  
Malee Seaview and Sai Naam Area  
2010-08-24**



**After installation  
G101**



**After installation  
G106**



**After installation  
G207**



**After installation  
G207**